






Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /  
 Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA, AD...



- 1 A 963 131 NU
- 4 A 963 132 NU
- 8 A 963 143 NU
- 9 A 963 146 NU
- 10 A 963 147 NU
- 14 A 960 890 NU
- 16 A 960 891 NU
- 17 A 960 706 NU
- 20 A 960 500 NU
- 21 A 963 335 NU
- 22 A 860 700 NU
- 23 A 960 893 XX
- 24 A 960 895 NU
- 25 A 962 390 XX
- 26 A 963 309 NU
- 27 A 963 054 NU
- 28 B 961 011 XX
- 29 A 960 704 NU
- A 962 476 NU
- 30 A 960 705 XX



**CONNECT BLUE**  
 A 5801 .. A5944 ..







0612 / A 866 525  
 (+ A 866 612)  
 Made in Germany






Ideal Standard International BVBA  
 Chaussée de Wavre, 1789 - box 15  
 1160 Bruxelles  
 Belgium

www.idealstandardinternational.com





		0	1	2	3	4	5	6	7	8	9
	°C	49,5	49,5	48	46	42,5	41	37	33,5	31	28
	°C	65	65	63,5	60,5	57	53,5	49	44,5	39	34,5
	°C	81	81	78,5	73	69	63,5	56	49	42,5	36



	<b>P</b>	bar		MAX. 10		5			<b>Q</b> (3 bar)
	<b>T</b>	°C		MAX. 80		65			<b>l/min</b>
						55			<b>25</b>