


Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdeler / Reservdeler / Varaosat /  
 Vraosat / Varahlutit / Αναλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Pieše de schimb  
 / Rendelhető alkatrészek / Запасні частини / Резервни делови / Резервни делови /  
 Резервни делови / Аtsarginiai dalij / Teilitavad varaosat / Резервну дају

XX = AA, AD...

- 1 = A 860 886 XX
- 2 = A 860 887 NU
- 3 = A 860 888 NU
- 4 = A 962 136 NU
- 8 = A 960 944 NU
- 13 = A 860 889 NU




	<b>P</b>	bar	MIN. 0,5	MAX. 10		<b>Q</b> (3 bar)	<b>l/min</b>	16
	<b>T</b>	°C	MAX. 80					



Ideal Standard International BVBA  
 Corporate Village - Gent Building  
 Da Vincilaan 2  
 1935 Zaventem  
 Belgium


[www.idealstandardinternational.com](http://www.idealstandardinternational.com)




## CERAPLUS

A 5776 .. A 5777 ..

1213 / A 866 498  
 (+ A 865 612)  
 Made in Germany



A 5776 ..



A 5777 ..

