





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi

XX = AA, AD,..


Position

- 2 = A 960 201 XX
- 3 = B 960 457 XX
- 6 = A 962 099 NU
- 9 = A 963 103 NU (2x)
- 10 = A 960 151 NU
- 11 = A 963 752 NU (2x)
- 12 = A 963 544 NU (4x)
- 13 = A 962 213 NU
- 14 = A 962 214 NU
- 17 = A 962 605 NU (2x)
- 18 = A 961 183 NU
- 19 = A 963 667 NU
- 20 = A 962 218 NU (2x)
- 21 = A 962 219 XX
- 22 = A 963 525 NU (3x)
- 24 = A 960 219 NU
- 25 = A 961 182 NU (2x)
- 27 = A 961 335 NU
- 29 = A 960 486 NU
- 31 = A 963 600 NU
- 32 = A 962 215 XX
- 34 = A 962 216 NU
- 35 = A 962 217 NU








CERAPLUS
 A 4152 .. A 4154 ..

0208 / A 865 824
 (+ A 865 612)
 Made in Germany



Ideal Standard
 Roentgenstrasse 9
 54516 Wittlich
 Germany





	P	bar				Q (3 bar)
	T	°C				l/min
						6