






Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA, AD...


- 1 B 960 948 XX
- 2 A 963 309 NU
- 3 A 963 054 NU
- 4 A 963 654 XX
- 5 A 963 176 NU
- 6 A 960 500 NU
- 8 A 961 302 NU
- 9 A 962 328 NU
- 10 A 960 304 NU
- 11 A 963 305 NU
- 12 A 963 600 NU
- 13 A 963 700 NU
- 14 A 963 699 NU
- 16 A 963 744 XX
- 18 A 963 799 XX
- 19 A 962 682 XX



CERASPRINT
 A 5727 ..


0121 / A 866 467
 Made in Germany





	P	bar				Q (3 bar)
	T	°C				l/min
						9



Ideal Standard International NV
 Corporate Village - Gent Building
 Da Vincilaan 2
 1935 Zaventem
 Belgium

www.idealstandardinternational.com





0,3 MPa 3 bar	50°C	16°C	°C										
			0	1	2	3	4	5	6	7	8	9	
	50°C	16°C	49,5	49,5	48	46	42,5	41	37	33,5	31	28	
	65°C	16°C	65	65	63,5	60,5	57	53,5	49	44,5	39	34,5	
	81°C	16°C	81	81	78,5	73	69	63,5	56	49	42,5	36	